




Legend

- Province
- Central Karoo - District Municipality
- Wards no - 7
- Beaufort West - Local Municipality

1. Safe and Stable Final Landform - The side walls of the final void were sloped and levelled. It is confirmed that the area is safe. The Mine Health and Safety Act, 1996 (Act No. 29 of 1996) compliance score of 5 was achieved, confirming the area was left in a safe, stable, and sustainable post-mining environment. (Reg 62(a); MHSA s.11) 2. Removal of Infrastructure and Waste - All mining equipment, infrastructure and other items used during the mining period were removed from the site. Waste material of any description, including receptacles, scrap, rubble and tyres, relating to the mining activities was also removed entirely from the mining area. (NEM:WA, Act No. 59 of 2008; Reg 62(c)) 3. Final Rehabilitation and Revegetation - The following rehabilitation measures were implemented in accordance with the general mine closure principles of the MPRDA and NEMA:• All infrastructure and waste materials were removed from site, and disturbed areas were rehabilitated to an acceptable standard.• Topsoil was replaced where available, and surfaces were stabilised to promote natural vegetation establishment.• All waste was disposed of at licensed facilities; no on-site disposal was permitted.• Rehabilitation of the surface area entailed landscaping, levelling, top dressing, land preparation, seeding (where required) and maintenance, and invasive plant species clearing.• Sufficient ground cover was established that minimised the risk of erosion. (NEMBA, Act No. 10 of 2004; Reg 62(d)) 4. Non-Polluting Post-Mining Environment - No Water Use Licence was triggered by the mining activities. Sufficient ground cover was established that minimised the risk of erosion and resulted in a safe and non-polluting environment that blends in with the surrounding environment. The area no longer presents an unacceptable environmental risk. (NWA, Act No. 36 of 1998; NEMA, Act No. 107 of 1998) 5. Landscape Integration - The rehabilitated area blends with the surrounding Karoo landscape. The final man-made landform is physically and environmentally stable and does not pose an unacceptable safety risk to humans or animals. (Reg 62(a)) 6. Post-Mining Land Use - The disturbed and subsequently rehabilitated area is capable of supporting appropriate post-mining land uses as undisturbed open land within the Beaufort West Local Municipality area. The permit holder has also rehabilitated the area that was unintentionally exceeded beyond the permit boundaries. No objections were raised by the Beaufort West Municipality or any Interested and Affected Party (I&AP) regarding the issuing of the closure certificate. (Reg 62(k))

Proposed mining area coordinates:
A22.571246°E32.346659°S22°34'16.49" E32°20'47.97" S
B22.571531°E32.346660°S22°34'17.51" E32°20'47.98" S
C22.571477°E32.346879°S22°34'17.32" E32°20'48.76" S
D22.571706°E32.347350°S22°34'18.14" E32°20'50.46" S
E22.570930°E32.348185°S22°34'15.35" E32°20'53.47" S
F22.569487°E32.348080°S22°34'10.15" E32°20'53.09" S
G22.569323°E32.347735°S22°34'09.56" E32°20'51.85" S
H22.570260°E32.347876°S22°34'12.94" E32°20'52.35" S
A 22.571246°E32.346659°S22°34'16.49" E32°20'47.97" S

Mining area:
±1.48 ha

Client:

Consultant: