SMIT GRONDWERKE (PTY) LTD, ON A PORTION OF REMAINING EXTENT OF PORTION 2 OF THE FARM 199RD, CLANWILLIAM, WESTERN CAPE PROVINCE

ENVIRONMENTAL PERFORMANCE ASSESSMENT / ENVIRONMENTAL AUDIT REPORT

DMR REFERENCE NUMBER:	WC 30/5/1/3/2/10219 MP
AUDIT PERIOD:	17 January 2023

PREPARED BY:

PREPARED FOR:

Smit Grondwerke (Pty) Ltd Contact Person: Mr TG Smit Tel: 027 482 1701 Fax: 027 482 1271 Email: <u>grondwerke@smiting.co.za</u> Postal Address: P.O. Box 249 Clanwilliam 8135



PREPARED BY: Greenmined Environmental Auditor: Murchellin Saal Tel: 021 851 2673 Cell: 076 792 6327 Fax: 086 546 0579 Postal Address: Suite 62 Private Bag x15 Somerset West 7129



1. PROJECT SPECIFIC DETAIL

ITEM	MINING PERMIT HOLDER				
Company Name	Smit Grondwerke (Pty) Ltd				
Contact Person	Mr. Tobias Gerhardus Smit				
Tel Number	027 482 1701				
Fax Number	027 482 1271				
E-mail Address	grondwerke@smiting.co.za				
Postal Address	P.O. Box 249 Clanwilliam 8135				
ITEM	CONSULTANT DETAIL				
Company Name	Greenmined Environmental				
Contact Person	Murchellin Saal				
Tel Number	021 851 2673				
Cell Number	076 792 6327				
E-mail Address	Murchellin.s@greenmined.co.za				
Postal Address	Postnet Suite 62 Private Bag x15 Somerset West 7129				
ITEM	LOCATION AND AREA INFORMATION				
Site Name	Tierkloof Sand Mine 2				
Property Description	Remainder of Portion 2 of Farm 199				
Location	The site is located ±740 m south-west of the N7 national road approximately 6.5 km north of Clanwilliam town.				
Size of Mining Area	4.9 ha				

TABLE OF CONTENTS

1. PROJECT SPECIFIC DETAIL	2
2. ENVIRONMENTAL AUDIT REPORT	4
PROJECT DETAIL	4
DETAIL OF AUDITOR	5
SCOPE & PURPOSE OF ENVIRONMENTAL AUDIT	5
ASSUMPTIONS, UNCERTAINTIES OR GAPS IN KNOWLEDGE	6
LOCATION	6
PROJECT DESCRIPTION	6
SITE CONDITIONS	7
REPORTABLE ENVIRONMENTAL INCIDENTS	
ADOPTED METHODOLOGY	8
COMMENTS OR COMPLAINTS RECEIVED FROM I&AP'S	
AUDITING OF EA, EMPR AND REPORTING THEREOF	
GENERAL REPORT	
ECO SIGNATURE	20
PHOTOGRAPHS	22

2. ENVIRONMENTAL AUDIT REPORT

PROJECT DETAIL

Permit Number:	06/2020 WC 30/5/1/3/2/10219 MP	Inspection Date:	17 January 2023
Site Name:	Tierkloof Sand Mine 2	Permit Holder:	Smit Ingenieurswerke & Transport CC
Report Number:	02	Other Authorisations:	LUPA: 12 August 2020



DETAIL OF AUDITOR

(APPENDIX 7 SUB-REGULATION 3(A) & (B)):

ECO:	Murchellin Saal				
EXPERTISE:	Mrs. MD Saal has 9 years of experience in environmental legal compliance audits, (GIS) geographic information system, mining right and permit applications and applications for environmental authorisations & Water use applications.				
DECLARATION OF INDEPENDENCE:	 I Murchellin Saal declare that – I act as independent environmental control officer in this compliance audit; I will perform the work relating to the audit in an objective manner, even if the results and findings are not favourable to the holder of the authorisation; I have expertise in conducting environmental compliance audits, including knowledge of the Act and regulations that have relevance to the activity; I will adhere to and comply with all responsibilities as indicated in the National Environmental Management Act and Environmental Impact Assessment Regulations. I do not have and will not have any vested interest in the activity other than remuneration for work performed in terms of the Environmental Impact Assessment Regulations, 2014 (as amended 2017). Matual Signature of ECO Date: 19 January 2023 				

<u>SCOPE & PURPOSE OF ENVIRONMENTAL AUDIT</u> (APPENDIX 7 SUB-REGULATION 3(C)):

This environmental audit report was compiled in terms of the requirements of the NEMA EIA Regulations, 2014 (as amended 2017).

OBJECTIVE:

The objective of the environmental audit report (EAR) is to evaluate compliance of the operational activities with the Environmental Management Programme Report (EMPR) and Environmental Authorisation as approved by the Department of Mineral Resources and Energy.

INSPECTED AREAS:

The inspection included an assessment of the following areas:

- Access road;
- Parking and
- Excavation area



In order to establish the environmental compliance assessment of the operation, the mining site was inspected on foot by the Environmental Control Officer, Murchellin Sal, of Greenmined Environmental accompanied by site management.

ASSUMPTIONS, UNCERTAINTIES OR GAPS IN KNOWLEDGE (APPENDIX 7 SUB-REGULATION 3(F)):

The assumptions made in this document, stem from specific information gathered during the site audit and background information gathered from site management. No uncertainties or gaps in knowledge could be identified that is applicable during this audit period.

Site Location:	The site is located \pm 740 m south-west of the N7 national road approximately 6.5 km north of Clanwilliam town.					
Site Map:						
	DECIMAL DEGREES	DEGREES MINUTES SECONDS				
Site	A -32.135141° S 18.843874°E A 32°08'06.508"S 18°50'37.946"E					
Coordinates:	B -32.136660° S 18.846964°E B 32°08'11.976"S 18°50'49.070"E					
	C -32.137598°S 18.846378°E C 32°08'15.353"S 18°50'46.961"E					
	D -32.135824°S 18.842260°E	D 32°08'08.966"S 18°50'32.136"E				

LOCATION

PROJECT DESCRIPTION

Smit Ingenieurswerke & Transport CC applied for environmental authorisation and a mining permit over 4.9 ha of the above-mentioned property that was approved in January 2020 (EA), and March 2020 (MP) respectively. A second renewal of the mining permit will be submitted in March 2023. The mining area is 4.9 ha and will be developed over an area currently used for agricultural purposes. The mining method is representative of the small scale mining industry where the mineral



(sand) is loaded with a front-end-loader (FEL) directly from the footprint area onto a truck that delivers it to the clients. Strip mining will be implemented with little to no stockpiling required. No washing of sand is needed. Due to the small scale of the operation no infrastructure will be established within the mining footprint. Prior to commencement of the mining activities the Farm owner cleared an area for potato planting. This area is now used by the permit holder for parking and toilet use. An agreement between the farmer and permit holder is included in the photo report. The proposed project does not require any electrical connections, and no chemicals will be stored on site. Vehicle/equipment maintenance will be done at an existing off-site workshop (Clanwilliam Town) of the permit holder, and the area will be reached via an existing farm road.

SITE CONDITIONS

Very warm sunny conditions

Incident Date: No environmental incidents were recorded during the audit period. Incident: How addressed: When addressed: When addressed:

REPORTABLE ENVIRONMENTAL INCIDENTS



ADOPTED METHODOLOGY

(APPENDIX 7 SUB-REGULATION 3(D):

COMPLIANCE SCORE	DESCRIPTION			
1	Task not achieved			
2	Task 20% achieved			
3	Task 50% achieved			
4	Task 80% achieved			
5	Task 100% achieved in accordance with the EMP			
NON-COMPLIANCE SCORE	DESCRIPTION			
	DESCRIPTION LOW – Mitigation not needed / mitigation measures to be maintained			
	LOW – Mitigation not needed / mitigation measures to be			

DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS	
	L	EGISLATION COM	PLIANCE:		
National Environmental Management Act, 1998 (Act No 107 of 1998) and the Environmental Impact Assessment Regulations, 2014 (as amended 2017).	5	-	Compliant	DMRE issued the operation with an environmental authorization (EA) on 27 January 2020.	
Copy of the environmental authorisation (EA) and EMPR available on site.	5	-	Compliant	A copy of the EA and EMPR is available in a site file at the Permit Holders offices in Clanwilliam.	
Mineral and Petroleum Resources Development Act, 2002 (Act No 28 of 2002).	5	-	Compliant	DMRE issued the operation with a mining permit (MP) on 10 March 2020. The first renewal of the permit was submitted to DMRE in February 2022, A second renewal will be submitted by March 2023.	
Mining permit (MP) available on site.	5	-	Compliant	A copy of the MP is available in a site file at the Permit Holders offices in Clanwilliam	
National Environmental Management: Air Quality Act, 2004 (Act No 39 of 2004).	N/A	-	-	The operations at the sand mine does not trigger the NEM:AQA, 2004.	
National Environmental Management: Waste Act, 2008 (Act No 59 of 2008).	5	-	Compliant	Although the operations does not require a waste use licence, refuse generated at the mine is handled in accordance with the NEM:WA, 2008.	
National Water Act, 1998 (Act 36 of 1998).	N/A	-	-	The operations at the sand mine does not trigger the NWA, 1998.	
National Environmental Management: Biodiversity Act, 2004 (Act No 10 of 2004) (NEM:BA).	5	-	Compliant	At the time of the inspection no listed invasive plant species were noted within the mining footprint.	
Hazardous Substances Act, 1973 (Act 15 of 1973).	N/A	-	-	No chemicals or hazardous substances are kept/stored at the mine.	
SOIL & AGRICULTURAL POTENTIAL (EMPR PG 52, 72):					
Topsoil stripping done (upper 300mm)	5	-	Compliant	The topsoil was stripped from the footprint prior to sand mining.	
Topsoil storage/stockpiling (<1.5 m high)	5		Compliant	The stripped topsoil was stockpiled.	



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS
Topsoil stockpiles protected and not used for any purpose other than rehabilitation.	5	-	Compliant	
Surface slope (even if minimal) maintained so the excavation is free draining.	5	-	Compliant	-
Areas with erosion reinstated.	5	-	Compliant	
Steep slopes reduced to a minimum and profiled to blend with the surrounding topography.	5	-	Compliant	
Topsoil returned to rehabilitated area.	N/A	-	-	
Topsoil spreading done at the end of the rainy season.	N/A	-	-	The permit holder will strive to replace the topsoil (over the rehabilitated area. This will come into effect per 1 hectare areas.
Soil stabilised upon topsoil spreading.	N/A	-	-	Not yet applicable.
Rehabilitated area monitored for erosion.	N/A	-	-	Not yet applicable.
	BIODI	VERSITY (EMPR P	G 36, 44 -49,57)	
Aliens & weeds controlled on site.	5	-	Compliant	At the time of the inspection no listed invader plants were noted within the mining footprint.
All animals, birds and reptiles protected on site	5	-	Compliant	-
Excavation providing an escape route for trapped animals.	5	-	Compliant	-
Excavation daily inspected for signs of trapped animals.	5	-	Compliant	-
Rehabilitated area covered with natural vegetation as required in the rehabilitation plan.	5	-	Compliant	Not yet applicable currently at 0.13ha extent. Rehabilitation as per EA will be implemented after each 1 hectare strips.
	AIR QUAL	TY & NOISE (EMP	R PG 45 – 51,55	
Dust suppression implemented.	5	-	Compliant	Although dust suppression wasn't needed at the day of the inspection, site management confirmed that it is implemented when needed.



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS
Footprint of cleared areas minimised.	5	-	Compliant	As mentioned earlier, it can be confirmed that at the time of
Five Mining strips rehabilitated as soon as mining is complete. (1hactare each)	N/A	-	-	inspection the mining extent is still below the 1hactares and therefore no rehabilitation has been necessary to date.
Speed of vehicles controlled to lessen dust generation and road deterioration	4	-	Partially Compliant	Although it was clear that the speed limits are adhered to the client was instructed to ensure that the signage boards are erected and placed where visible.
Activities reduced during strong winds.	5	-	Compliant	-
Noise control implemented (no loud music).	5	-	Compliant	-
Mining equipment serviced regularly to ensure noise emissions are minimized	5	-	Compliant	-
Operation hours restricted as stipulated in the EMPR.	5	-	Compliant	The Applicant, and the sand mining operation will take place during normal working hours (no work on Sundays).
	WASTE MA	NAGEMENT (EMP	R PG 44, 46, 94	- 64):
Workers provided with environmental awareness training.	5	-	Compliant	Proof of Awareness training included in photo report.
Waste collected in sealable containers.	5	-	Compliant	General waste is removed to the Permit Holders offices in Clanwilliam where it is incorporated into the municipal waste removal system. Very little waste was generated to date.
Site free of day-to-day litter.	5	-	Compliant	Site was neat and clean.
General waste dumped at a recognised landfill site.	5	-	Compliant	General waste is removed to the Permit Holders offices in Clanwilliam where it is incorporated into the municipal waste removal system. Very little waste was generated to date.
Hazardous waste removed by a registered waste handling contractor.	N/A	-	-	No hazardous waste has been generated at the site.
Spillages not disposed of into the environment, ditches, drains or water courses.	N/A	-	-	Not applicable as no spillages occurred during the audit period.
No waste stockpile area allowed outside the boundaries of the mining area.	5	-	Compliant	-



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS
Proper sanitation facilities available to employees.	5	-	Compliant	A chemical toilet is present at the parking area outside of permit area. This area was agreed between permit holder and farm owner. Proof of agreement in photo report. Bastech Hire (Pty) Ltd will be responsible for once a month cleaning.
Chemical toilet secured to the ground.	5	-	Compliant	A photo of the toilet is included in the photo report.
	HERITAGE RE	SOURCES (EMPR	PG 43, 60, 96,1	
Archaeological-, heritage and/or cultural remnants protected.	N/A	-	-	No archaeological or cultural remnants were discovered during the audit period.
	SOCIO-EC	ONOMIC MATTERS	6 (EMPR PG 48,	58):
Complaints register on site.	5	-	Compliant	The complaints register is kept at the site office of the Permit Holder in Clanwilliam, as the mine is on private property and not accessible to the general public. To date no complaints were received.
Notice board (with contact details) erected and maintained at the site entrance.	3	-	Partially Compliant	Notice board for 10219mp to be erected and placed on outside fence, permit holder to remove old permit board.
Mining area rehabilitated to post-mining land use capability.	N/A	-	-	Not yet applicable.
MAN	AGEMENT OF FUEL	AND HAZARDOU	S PRODUCTS (EMPR PG 27,136):
Sealed drip trays used and managed on site.	3	-	Non- Compliant	No drip trays were present at the time of inspection.
Mining equipment mechanically sound without visible oil leaks.	5	-	Compliant	At the time of the inspection, this appeared to be true.
Regular maintenance of mine equipment done in Clanwilliam at the Permit Holders offices.	5	-	Compliant	-
Complete oil spill kit/absorbent material available on site.	5	-	Compliant	-
Hazardous material stored within a bunded area (110% capacity).	N/A	-	-	No hazardous material is stored within the mining area.



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS			
Management of fuel and oil spills	5	-	Compliant	At the time of the inspection no oil/fuel spills were noted.			
	FIRE	MANAGEMENT (E	MPR PG 197):				
Firefighting equipment available on-site (2x rubber beaters and 1 fire extinguisher).	5	-	Compliant	Although the Permit Holder does not have fire beaters, the machinery all have fire extinguishers.			
Fires contained to facilities specially constructed for the purpose	N/A	-	-	No open fires are allowed at the mine.			
Employees trained in firefighting	5	-	Compliant	One employee is fully trained.			
Major fires or explosions reported.	N/A	-	-	No fire/explosion occurred during the audit period.			
	MINE & EQU	IPMENT MANAGE	MENT (EMPR P	G 58):			
Mining area demarcated with visible beacons	3	-	Partially Compliant	At the time of inspection only two beacons were visible. Client will ensure the other two beacons are placed and visible.			
Is the contractor implementing good visual and housekeeping standards.	5	-	Compliant	At the time of the inspection the site was found to be very neat and well managed.			
Mining contained to designated mining area.	5	-	Compliant	At the time of the inspection mining was contained to the approved boundaries. Mining currently takes place at a maximum of three times per week. The parking area and toilet is currently outside of the permit area on an area as per agreement between the permit holder and farm owner.			
Unnecessary surface disturbance avoided.	5	-	Compliant	-			
Incident register available on site.	5	-	Compliant	The incident register is kept at the Permit Holders offices in Clanwilliam.			
ACCESS	ACCESS ROADS, VEHICLES & TRANSPORTING OF MATERIAL (EMPR PG 24,50,97):						
Access road maintained.	5	-	Compliant	-			
Movement of project related vehicles and machinery restricted to the approved mining area. No crisscrossing through undisturbed areas.	5	-	Compliant	-			



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS	
Sand transported from site by the Permit Holder. No clients collecting directly from the mine.	5	-	Compliant	-	
Speed limit enforced (20 km/h) along the access road.	3	-	Non- Compliant	Speed limit is enforced. However, to ensure this is priority permit holder must erect notice boards.	
	EMPLOYEE AN	ID SAFETY MANA	GEMENT (EMPI	R PG 64):	
Workers inducted and informed of EMPr conditions	5	-	Compliant	All site workers did receive induction training and signed document included in photo report.	
Proof of training available	5	-	Compliant	-	
Workers provided with PPE	5	-	Compliant	-	
Are there signs present, indicating the mining site and speed restrictions.	5	-	Compliant	-	
Effective access control to prevent unauthorised entry.	5	-	Compliant	There are three lockable gates leading towards permit area.	
EA SPECIFIC CONDITIONS (NOT YET INCLUDED EARLIER):					
Mining activities conducted in accordance with EMP and layout.	5	-	Compliant	Although the mining direction and access road has changed the strip mining method is still in place and the access road currently used was approved by department of transport and does not trigger a listed activity.	
After mining the final slopes/levels must be to the level of the surrounding natural ground level.	N/A	-	-	To be implemented during the decommissioning / closure phase.	
No mining may occur within 40 m of the bank of the stream.	5	-	Compliant	-	
Uncontaminated storm water must be prevented from coming into contact with the waste and must be diverted away from the storage site and mining area.	5	-	Compliant		



DESCRIPTION	COMPLIANCE SCORE	NON- COMPLIANCE SCORE	STATUS	COMMENTS
The Holder of EA must appoint an ECO, provide his name and contact detail to the RM and ensure that the ECO is always available on site.	5	-	Compliant	ECO appointment and Enactment letter sent to Dmre 24 January 2022.
Annual EAR (environmental audit report) submitted to DMR.	5	-	Compliant	This report is the 1 st report and will be submitted in February 2022 with the renewal and financial reports.
Annually assess the environmental liabilities of the operation regarding the financial provision for rehabilitation.	5	-	Compliant	
Notify DMR within 24 hours of any incident occurring.	N/A	-	-	No incidents to date.
Mining area fenced off with lockable gates.	5	-	Compliant	There are at least 3 lockable gates.
Water proof, durable and legible notices in at least 3 official languages displayed at the entrance to the site.	3	-	Partially Compliant	Permit holder to place notice for Grondwerke.
Emergency preparedness plan available.	5	-	Compliant	
Access Road	5	-	Compliant	As per the SANRAL approval attached the permit holder is using the existing access road.

<u>COMMENTS OR COMPLAINTS RECEIVED FROM I&AP'S</u> (APPENDIX 7 SUB-REGULATION 3(G) & (J)):

No written environmental related complaints were received during the audit period.

AUDITING OF EA, EMPR AND REPORTING THEREOF (REGULATION 34):

Date of previous	
EAR/EPA:	1 st EPA – February 2022
Proof of	1 st EPA – February 2022
submission to	
DMRE available:	
EAR/EPA compiled	
by independent	The 2022 EPA was compiled by Mrs. M Saal from Greenmined
person with	Environmental (Pty) Ltd.
environmental	
auditing expertise:	
Potential and	
registered I&AP's	The EPA is available at the Permit Holders office in Clanwilliam.
notified within 7	
days of the	
submission date,	
and report available	
on publicly	
accessible website	

GENERAL REPORT

Compliance of the mining site with the EMPR (2019) was reviewed during the site assessment. The mining area recorded a compliance score of 98.15% for the audit period .

The initial road as per EA approved by Dmre was not approved by SANRAL. Proof letter included in Photo repor The permit holder is therefore using the initial access road as approved for the now closed permit 10111MI which is based on the same Farm. The existing road therefore does not trigger any listing notices.

The below image was the initial mining route suggested in the FBAR. However, it should be noted that due to the change of access road it was found to be more practical to start from the top closer to the access road currently in use. Mining will therefore work from block 5-1.






Figure 1: Image taken from the Basic Assessment Report, 2019 showing the locality and strip mining direction of the footprint area and existing access road.



Figure 2: Image based on the Basic Assessment Report, 2019

The image above shows the currently used access road based on the outcome of SANRAL decision. The mining direction have therefore been changed to suite the site structure from block 5 towards block 1. In terms of Section 43(4) of the Mineral and Petroleum Resources Development Act, 2002 (as amended) (hereinafter referred to as the "MPRDA"), an application for a closure certificate must be made to the Regional Manager in whose region the land in question is situated within 180 days of the occurrence of the lapsing, abandonment, cancellation, cessation, relinquishment or completion contemplated in subsection 3. Therefore, the 180-day period as contained in Section 43(4) of the MPRDA already commenced upon the lapsing of the 3nd renewal period.

Waste Management:

- General waste to be removed from site to permit holder office from where it is then removed to a
 recognized landfill site. To date no waste was removed from site and therefore no documentation proof
 is included.
- Chemical toilet will be cleaned by Bastech Pty Ltd. To date no cleaning has been deemed necessary.

DOCUMENT CHECKLIST:

Environmental Authorisation	-	Present
Mining Permit	-	Present



	Approved EMPR	-	Present	
	Regulation 2(2) Mine Plan	-	Present	
	Financial Provision Calculation	-	Present	
	Environmental Assessment Report	-	Present	
	Incidents register	-	Present	
	Complaints Register	-	Present	
	Environmental Awareness Training	-	Present as part of the EMPR	
	Emergency Preparedness Plan	-	Present	
	Waste Registers	-	Present	
	Environmental Audit Checklist	-	Present	
	SANRAL approval	-	Present	
NE	NEED FOR AMENDMENT OF THE EMPR:			

No need was identified for the amendment of the EMPR.

FINANCIAL PROVISION:

The 2nd calculation was completed in January 2023 as the Tierkloof Sand Mine 2 was reviewed as part of this year's (2023) annual environmental audit and the financial provision amount came to R 5 161 .47.

The 2023 financial provision does not exceed the value of the guarantee in place with the DMRE (R 70 000), and therefore the permit holder does not have to provide a shortfall. The financial provision calculation will be submitted to DMRE with this EAR/EPA.


The permit holder has a bank guarantee to the value of R 70 000 with the DMRE.

ECO SIGNATURE

NAME:	SIGNATURE:	DATE:
Murchellin Saal	Mad.	19 January 2023

ACCES	S ROAD

PHOTOGRAPHS






MINING	MINING AREA					
MINING EC	MINING EQUIPMENT					









2002 to (but name) [SMIT GROMP Interrity number in case of a natural pr in the case of a percent data in a OP Co * If other, sportly Registrations manufact of the manufacture of co- on Co. To mixe for justice of relevant] [SMI Co [All series of the anited additions, i all indicated on the attached plan Na. United for the data of localing to orth which may not exempt the heldon This permit does not exempt the heldon	TBILA Image:	<image/> <image/> <image/> <image/> <text><text><text><text><text><text><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></text></text></text></text></text></text>	
	Mining Permit	Environmental Authorization	



<image/> <text><text><text><text><text></text></text></text></text></text>				
Then STAND Judi The Series Stress: Darr Merterblander Darr Merterblander Break deterblander Bre		Date: 10 March 2030	Direct Line: +27 (0) 21 957 4600	BUILDING SOUTH AFRICA
Did Grey Street STRAND Total				
<text><text><text><text><text><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></text></text></text></text></text>		106 Grey Street		
<text><text><text><text><text><text><text><text><text><text><text><text></text></text></text></text></text></text></text></text></text></text></text></text>				
Dear Me Terblanche MCTONAL, ROUTE 7 SECTION 4: PROPOSED SAND MINING OPERATION ON PORTION 2 OF FAMM 139, CLANNILLAMM (004 4.83) The above application has reference. The South African National Roads Agency SOC Limited (SANRAL) does not support a business access at km 4.8. SANRAL will consider a new access farther to the north where sight distance is better and the road only has one in each direction. Torus Sincerely Advances Fak Rok STATUTORY CONTROL 25 578579 Membrane Internet May - <u>Jesterel Biotecns</u> (1918) Membrane Internet May - <u>Jesterel Biotecns</u> (1918) Membrane Internet May - Jesterel Biotecns (1918) Membrane Internet Membrane Internet May - Jesterel Biotecns (1918) Membrane Internet May - Jesterel Biotecns (1918) Membrane Internet Membrane Internet May - Jesterel Biotecns (1918) Membrane Internet May -				
Dear Mar Terriblanch Antitional, ROUTE 7 SECTION 4: PROPOSED SAND MINING OPERATION ON PORTION 2 OF FAIRM 19, CLANWILLIAM (MA 4.83) The above application has reference. The South African National Roads Agency SOC Limited (SANRAL) eves not support a business access at im 4.81. SANRAL will consider a new access further to the north where sight distance is better and the mod only has nor lare in each direction. Tours Sincerely Martan R & Kock STATUTORY CONTROL 0: Status Martan Bar, Jeanne Baya – jeanne Bay				
Antional, Route 7 Section 4: PROPOSED SAND NINING OPERATION ON PORTION 2 OF FAMM 190, CLANWILLIAM (CM 4.83) The slow application has reference. The South African National Roads Agency SOC Limited (SANRAL) does not support a business access at im 4.84. SANRAL will confider a new access further to the north where sight distance is better and the road only has one ine in each direction. Tours Sincerely Adv Kork Manual Road Manager: Informed Boxers Loads Strate Manager: Informed Boxers Loads Distance Informed Boxers Loads Manager: Informed Boxers Loads Distance Informed Boxers Loads Manager: Infor			Email: admin@	tolan.co.za
CLANNIFLIAMM (KM 4.63) The source application has reference. The South African National Reads Agency SOC Limited (SANRAL) does not support a business access at km 4.8. SANRAL will consider a new access further to the north where sight distance is better and the road only has one lane in each direction. Torus Sincerely Advanced Torus Sincerely Advanced Torus Manager: Jerome Bays – journell Genergy Loss. 2: 573678 Torus Manager: Jerome Bays – journell Genergy Loss. Bays (Manager: Jerome Bays – journell Genergy Loss. 2: 573678		Dear Me Terblanche		
The South African National Roads Agency SOC Limited (SANRAL) does not support a business access at kin 4.8. SARRAL will consider a new access further to the north where sight distance is better and the road only has one are in each direction. Tours Sincerely Advance Rok Rod STATUTORY CONTROL 3: 53:65:7			4: PROPOSED SAND MINING OPERATION	ON PORTION 2 OF FARM 199,
SANAL will consider a new access further to the north where sight distance is better and the road only has one lane in each direction. Tours Sincerely M.M.M. R & Kock STATUTORY CONTROL 		The above application has referen	nce.	
Instein nacht direction. Furst Sincerely Fade Kock FATUTORY CONTROL Ca. Route Manager: istorne Buys – <u>internell förverun co.ta</u> To 579578 Methode Sinder Sin		The South African National Roads	Agency SOC Limited (SANRAL) does not supp	ort a business access at km 4.63.
Address R & Rock Distribution Cr. doute Manager: 10 573657	5		ss further to the north where sight distance	is better and the road only has one
STATUTORY CONTROL c. Route Manager: Jerome Buys – <u>intermedi deversa co.in</u> 19 5736574 Menne Agent : Hennes forst, Ondek, Molin, HB Henne Hag 12, Molin, Sont Mins, HB Terr/2013 HB HB. Hennes (19 12 HB Henne Hag 12), Hennes Hag 12, Molin, Sont Mins, HB Terr/2013 HB HB. Hennes (19 12 HB Hennes Hag 12), Hennes (19 12 HB Hennes (19 12 HB Hennes Hag 12), Hennes (19 12 HB Hennes Hag 12), Hennes (19 12 HB Hennes Hag 12), Hennes (19 12 HB Henne		Yours Sincerely		
Bardin Belgeneration (), Mit Mannener, BED, Mit Franzel, Mit Hauste, Mit Hauste, Mit Hausten, Mi		STATUTORY CONTROL cc. Route Manager: Jerome Buys J	en er er efte Geverge, co. La	
Borning für Fillward (Dargerent, die 3 Mannew (EE), die Fillwarde, bie Fillwarde, bie Fillwarde, für				
Ra In Indentities in agenty of the Dashbarre of Tangant.		Brial shigher states (Yell is at shreas related		
Scan with Fast Scan				Innal Company, Incustory, Mark Mathew
Scan with Fast Soan		the second se	per l	
				Tage Tart L
				🛒 Scan with Fast Soan
				r 9






SMIT GRONDWE SAND MINE, ON A PORTION OF REMAIN FARM 199RD, CLANWILL EMERGENCY PREPA	IING EXTENT OF PORTION 2 OF THE IAM, WESTERN CAPE	Ref No.: WC 30-5-1-3-2-10219 MP
		Department of Mineral Resources 25 January 2022 Attentury House Grit Riebeeck Street and Lower Burg Street Gape Town Western Cape Attention: Ms Sonia Mothodini LETTER OF ENACTMENT FOR MINING PERMIT WC 30-5-1-3-2-10219 MP ON A PORTION OF REMAINING EXTENT OF PORTION 2 OF THE FARM 199RD, CLANWILLIAM, WESTERN CAPE PROVINCE. This letter serves to inform the Department of Mineral Resources that the applicant, Smit Grondwerke (Pty) Ltd streted the operation in October 2021.
DMR REFERENCE NUMBER:	WC 30-5-1-3-2-10219 MP	The holder of the sand mining permit appointed Greenmined Environmental (Pty) Ltd to inform the DMR that the on-site ECD of the operation, in accordance with clause 4.10 of the Environmental Authorisation, is MT TG Smit
VERSION:	JANUARY 2022	with ID number 8009105173085. Contact Details:
PREPARED FOR: Smit Gonadweike (Pty) Ltd Contact Person: Mr GALJ Smit Tei: 027 482 1701 Faa: 027 482 1701 Email: 027 482 1271 Email: 027 482 1271 E	PREPARED BY: Greenmined Environmental Auditor: Wrs M. Saal Tel: 021 851 2673 Cel: 076 792 6327 Ex: 036 546 0579 Postal Address: Sufe 62 Private Bag X15 Somerset West 7129	 Tel: 027 482 1701 Cel: 082 895 6923 Email: <u>debiteure@smiting.co.za</u> Annual inspections and reports will be submitted to the DMR and will be done by Greenmined Environmental in accordance with the Environmental Authorisation. Consultant details: Mrs. Murchellin Saal Cel: 076 792 6327 Email: <u>Murchellin singreenmined.co.ta</u> Should the above information need to be submitted to any other entity or party, kindly provide writer hereof with the necessary details. the goal isn't to live forever, it is to protect a planet that will Greenmined Environmental (Pty) Ltd [Tel: 021 861 2873 [Fax: 086 646 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, AECD 8(in, Bark Square, Fax: 080 546 0679 Unit M01, Office M03, Bark Square, Fax: 080 548 0679 Unit M01, Office M03, C Weideman Reg N0: 201205666607 VAT No. 444026002
Emergency Prep	ardness Plan	Enactment and ECO letter



SMIT GRONDWERKE (PTY) LTD, ON A PORTION OF REMAINING EXTENT OF PORTION 2 OF THE FARM 199RD, CLANWILLIAM, WESTERN CAPE PROVINCE ENVIRONMENTAL AUDIT CHECKLIST	GENERAL WASTE DISPOSAL REGISTER SAND MINE, ON A PORTION OF REMAINING EXTENT OF PORTION 2 OF THE FARM 199RD, O
DMR REFERENCE NUMBER: WC 30/5/13/2/10219 MP AUDIT PERIOD:	DISPOSAL DATE DISPOSAL SITE QUANTITY DISPOSED WASTE TYPE RECEIP HAZARDOUS WASTE DISPOSAL REGISTER HAZARDOUS WASTE DIS
PREPARED BY: Smit Grondwerke (Pty) Ltd Contact Person: Mr TG Smit Tel No: 027482 1701 Cell No: 082 805 6923 Email: debiteure@smiting.co.za	DISPOSAL DATE DISPOSAL SITE QUANTITY DISPOSAL DATE QUANTITY DISPOSAL SITE QUANTITY DISPOSED WASTE TYPE RECEIPT
Environmental Audit Checklist – 2022-23	General and Hazardous waste register







CONFIRMATION OF CONTRACTORS AWARENESS OF EMP MINING PERMIT TO MINE 4.9 ON A PORTION OF REMAINING EXTENT OF PORTION 2 OF THE FARM 199RD, CLAN CAPE PROVINCE		10 FEBRUARY 2022 REFERENCE NUMBER: WC/30/5/1/3/2/10219MP	
NAME OF PERSON	INDUCTION MEETING	DATE OF MEETING	
Bernard Smit	Environmental Induction) 28 Januarie s	To Whom this may concern:
Chrisjan Nel	En vironmental Induction	23 Januarie 2	We, Gerrit Erasmus & Hester Susanna Smith the landowners of remainder of portion 2 of the farm 199, Clanwilliam district, Western Cape province.
Eugene Fortui	En vi ronmental Induction 11 Environmental Induction) 28 Jonuarie 2	I hereby want to bring it to your attention that the loading zone shown in attached picture is part of a potato plantation circle that will be planted after mining term has been completed, thereof Smit Grondwerke[PTY] LTD is allowed to park and load at this space. Any thru paths on plantation circles are allowed and won't disturb any aspect of our agricultural ground. This is part of our agricultural development.
			Landowner: Crevent Exasmus Smithe in print) Hester Suscemes Smith Signature: JAH MAN
			Date: u cz izezz
Confirmatio	on of Contractors Awareness of E Environmental Training	MP and	Agreement between Farm owner and Permit holder (11/02/2022)